

Replacement encoder kit for synchronous motors  
1FT/1FK Shaft heights 48/63/80/100: AS20DQI-88  
DRIVE-CLIQ Electronic rating plate identical to encoder  
with MLFB suffix 1 In spare part scenario delivery  
without motor data Upload data on site see SIOS ID  
59459190

## Further information

**Industry Online Support (Manuals, Catalogs, Certificates, FAQ, ...)**

<https://support.industry.siemens.com/cs/products?mfn=ps&lc=en-WW>

**Industry Mall (Online ordering system)**

<https://mall.industry.siemens.com>